Inblokken UGFW t.b.v. werkzaamheden **Hazard Analysis** Alternative Isolation Method: Blokafsluiter (BW) dicht met single bleed via brandkraan (BK). for Alternative Beiden voorzien van Rode Label. **Isolation Method** Reason for Alternative Isolation Method: The L3G_06.05.C.02_Veilig_entree policy requires a CSE procedure to include: Air gap (met misalignment), OF; i. afsteken of afblinden, OF: ii. Double Block & Bleed, goedgekeurd door een secundaire 111. goedkeurder voor veilig entree, OF: een gevarenanalyse uitvoeren, waarbij: iv. De alternatieve veiligstelmethode wordt beschreven, EN; a. de risico's die gepaard gaan met de alternatieve b. veiligstelmethode worden beoordeeld, EN; methoden worden geïmplementeerd om de risico die c. gepaard gaat met de alternatieve veiligstelmethode te beperken, EN; d. deze wordt goedgekeurd door De Facility/Work Group Leader (FWGL), EN; 2. de Responsible Care Leader (RCL) of gedelegeerde ([Nederland]1 Emergency Manager van dienst). For fire water lines, option i, ii and iii are not possible or desired. i is not possible because the lines are in the ground, therefor mis alignment cannot be achieved ii is not possible because each attempt to place a blind, would result in another CSE and therefor a never ending circle iii is possible but a) would result in a higher process safety risk due to the blocking of larger portions of the fire water grid. These systems could be impaired, but each impairment only reaches to 80% of the original protection. b) the impairments need to be activated by hand, resulting in a longer duration of time before an fire or emission is mitigated. c) poses a personal safety risk due to hoses on the ground and extra manhours to put those in place. Therefor option iv is needed. **Describe how this Describe the Hazard(s) Describe Methods Used to Mitigate the** alternative created if the failure Hazard Associated With Failure of the isolation method **Isolation Method** happens could fail. Instantaneous Exposure to high water Use of block valves with a low failure of block pressure (10 bar) failure rate (gate valves and valve butterfly valves). Test if all the pressure left the system after blocking, by opening a hydrant. Only sign the IOES Red label master list, if the

	system is free of pressure and the valves are not leaking.
	 Make sure that failure of a block valve is noticed by opening a hydrant and label it in open position.
	• If possible, open multiple hydrants between the CSE location and the block valve.
Approved by MOC nr: <u>EH&STNZ2020060033</u>	

Document history

The following information documents at least the last 3 changes to this document, including procedure reviews, with all the changes listed for the last 6 months

Datum	Naam	Wijzigingen
5 januari 2024	UA18714	Document review, no changes